



**NOTICE FOR DIRECT CONTRACTING
(Section 50 of RA 9184)**

THE DEPARTMENT OF AGRICULTURE, RFO 5, THROUGH THE 2021 RICE FPMA PROGRAM INTEND TO APPLY THE APPROVED BUDGET FOR THE CONTRACT (ABC) IN THE SUM OF TWO HUNDRED SIXTY PESOS ONLY (₱260,000.00) FOR PAYMENT FOR THE LABOR AND SUPPLY OF MATERIALS FOR THE REPAIR OF ONE (1) UNIT BRANSON TRACTOR ASSIGNED AT DA-RFO 5 PURSUANT TO DIRECT CONTRACTING UNDER SECTION 50 OF RA 9184 AND ITS REVISED IRR

PARTICULARS		UNIT COST	TOTAL COST
<u>Labor and Supply of Materials for the Repair of BRANSON TRACTOR (Model: f3625r)</u>			
SCOPE OF WORK	PARTS TO BE REPLACED		
* Check of Fuel Pipes & Clamp Bands	- Sub tank cooling water	3,089.00	3,089.00
* Change of engine oil	- Air cleaner assembly	14,471.00	14,471.00
* Cleaning of Air Cleaner Element	- Battery	16,022.00	16,022.00
* Check of Battery Electrolyte level	- Cap Fuel	16,500.00	16,500.00
* Check of Fan belt tension	- Clutch housing	16,806.00	16,806.00
* Check of Radiator hoses and clamp bands	- Clutch disc assembly	19,484.00	19,484.00
* Check of intake air hose	- Hydraulic Filter	4,418.00	4,418.00
* Replacement of oil Filter cartridge	- Mesh Dust	4,698.00	4,698.00
* Replacement of fuel Filter Cartridge	- Rear Tire	97,944.00	97,944.00

