



Republic of the Philippines
DEPARTMENT OF AGRICULTURE
Regional Field Unit No. 5
San Agustin, Pili, Camarines Sur

BILL OF QUANTITIES AND BID COST PROPOSAL

Project Title : SHEEP HOUSE REPAIR Classification : Production Facility
Project Location : DA RFO 5 COMPOUND, SAN AGUSTIN, No. of Unit : 1.00
PILI, CAMARINES SUR Net Length : _____
Appropriation : _____ Project Duration : 3 calendar days
Source of Fund : NDRRMF Starting Date : upon receipt of NTP
Scope of work/
Project Description : Replacement of damaged roof, fascia board and flashing

ITEM NO.	DESCRIPTION	QUANTITY	UNIT	TOTAL COST
I	: SCAFFOLDING	1	lot	_____
II	: REMOVAL WORK	1	lot	_____
III	: ROOF AND FASCIA REPAIR WORK	5	sq.m.	_____

AMOUNT IN WORD: _____

NAME AND SIGNATURE
OF CONTRACTOR : _____



Republic of the Philippines
DEPARTMENT OF AGRICULTURE
Regional Field Unit No. 5
San Agustin, Pili, Camarines Sur

Project Title: **Sheep House Roofing Repair**
Location: **DA RFO V, San Agustin, Pili, Camarines Sur**

