



* Cleaning of Fuel Filter	- Tube Rear	3,885.00	3,885.00
* Cleaning of water jacket (radiator interior)	- Disc Friction	3,903.00	3,903.00
* General Check-up	- Plate	3,221.00	3,221.00
	- Front Tire	47,806.00	47,806.00
	- Tube Front	5,546.00	5,546.00
	- Oil Filter	2,207.00	2,207.00
		TOTAL	₱260,000.00

Delivery Site/ Delivery Period:

Department of Agriculture RFO 5, San Agustin, Pili, Camarines Sur. Contract Duration is for 30 Calendar Days.

As such **BRIXTON CONSTRUCTION & INDUSTRIAL SUPPLY CORPORATION.,** 142 Kamias Cor. Anonas East Kamias 3, Quezon City, is hereby requested to submit the following documents:


1. Mayor's Permit
2. PhilGEPS Registration
3. Annual Income Return
4. Omnibus Sworn Statement

The bidders are required to pay Php500.00 for bid documents to the Cashier's Office, DA RFO-5, Pili, Camarines Sur. **All submitted documents must be in duplicate and marked with index/ear tabs or side-end tabs to identify the page components**, otherwise, bids will be automatically rejected on the ground of non-compliance with the prescribed bid requirements.

Sealed quotation must be received by BAC Secretariat, DA RFO 5 not later than **10:00 in the morning of 26 November 2021** at DA-BAC Office, DA RFO 5, Camarines Sur.

Let this Invitation be posted pursuant to RA 9184 and its IRR. For more information, please see or call BAC Secretariat, Legal Office, Tel. No. (054) 477-33-56.

November 19, 2021. San Agustin, Pili, Camarines Sur


LUZ R. MARCELINO
 RTD for Operations
 BAC Chairman
 †

